SV-0808M Final Report Site: Manus Dates on Site: 18 - 29 August 2008 Team Members: Required Items & Other Actions: MMCR waveguide & cables - MR to hand-carry from Darwin Troy Culgan

• Power line - KK to purchase and ship

• AWS METconsole computer from Darwin, prepare and ship - KK

DS hardware from MacDuff (on site)

• DS hardware procedures from MacDuff (on site)

• Fiber cable for E-Van from Darwin (on site)

• Arrange for local contractor to do I/D-Van floor during visit.

• Equipment from Eagan for coms check between Lombrum and Momote

• MPL serial cable ship from Darwin - KK

Procure PBX system in Darwin for Manus - KK

Procure & ship Kiosk UPS battery to Manus - KK

MET MI70LINK software & cable (en route)

Procure and ship BBSS GCS molecular sieve desiccant - TC to hand-carry 2 jars, ship 1 jar (on site)

MMCR tool kit (on site)

Task Summary: Safety:

Mike Ryczek

Kevin Widener

Major Hazards: Caustic chemicals (KOH), Explosive gas (H2), AC electricity

Hazard Controls: BOM Electrolyser Handbook, BM Electrolyzer Operations/Maintenance Training,

ASNZS 4836/2001-Safe Working on LV Electrical Installations, 2-man rule

When replacing items (e.g., desiccant, filters, etc.), record and report the quantity of spares left on site

SITE TASKS

High priority / usually non-routine Low priority / usually routine Completed

Priority	System	Date Completed (dd/Month)	Service Time (hours)	Tasks For each priority item insert new line (row) for each date/time entry
1	DS			Upgrade DS hardware - Contact mentor (Macduff)
		18-Aug	1	Hardware located and removed from packing crates
		19-Aug	4	Hardware installed and Matt Macduff, Dick Eagan notified
		23-Aug	2	Error on boot up, Matt contacted
		24-Aug	3	Worked with Matt to resolve problem, Disk reinitiating in progress
		26-Aug	2	Store vault to be sent to Darwin for diagnostics
2	MMCR	_		Replace waveguide & cables w/ Widener
		18-Aug		Cables yet to be located
		19-Aug		Cables located in Darwin office
		20-Aug		Kevin Widener installed one cable using PNNL stock from
				calibration kit
3	WND			Lower MET tower, hold each anemometer still, view data to see if
				one reports about 0.3m/sec (it should be 0.0), and troubleshoot
		22-Aug		Mast lowered and anemometers held still, upper wind speed 0
				lower wind speed read up tp 4m/s at times
4	MET			Install MI70LINK software & RS-232 cable
		18-Aug		For use during calibration site visits by technician
5	VANS			Oversee local electrician install of small switch board in storage
				can to separate light & power circuits
				Local electrician unavailable during this site visit
6	ORG			Connect ORG lens heater cable
		18-Aug	0.5	Lens heater cable connected
7	ORG			Replace ORG cable
		18-Aug	0.5	ORG cable inspected, OK

	SITE TASKS					
	High priority / ι	sually non-routine	Low p	oriority / usually routine Completed		
Priority	System	Date Completed (dd/Month)	Service Time (hours)	Tasks For each priority item insert new line (row) for each date/time entry		
8	OTHER			Check ARM Kiosk		
		20-Aug		Kiosk continued operation to be reviewed		
9	OTHER			Replace ARM Kiosk UPS battery		
		20-Aug		Not required until Kiosk review complete		
10	PWR	00.4	4	Relocate power line under new canopy		
		22-Aug	1	Locate required materials		
		23-Aug	4	Power cable in place awaiting local electrician to complete installation		
11	VANS			I- and D-Van floor repair		
				Insufficient time and local labor not available during this site visit		
12	IOP-MJO			Test coms between Lombrum and Momote for Chuck Long IOP in 2010 - LJ to follow up		
				?		
13	AWS			Replace METconsole laptop with a dedicated computer		
		19-Aug	3	Metconsole PC reloaded with Corepc and Metcosole software installed.		
14	OTHER			Install time card system w/ Hymson's coordination		
		20-Aug		Under review by LJ		
15	COMM			Troubleshoot Iridium phone		
		17-Aug		Larry has found no fault during use		
16	COMM			Troubleshoot D-Van Internet connection		
		19-Aug	1	D-Van internet connection working after system checks by Dick Eagan		
17	COMM			Replace VSAT antenna bolts (bolts should be on site)		
		20-Aug	8	In progress		
		21-Aug	6	Completed		
		26-Aug	2	Check antenna alignment		
18	TSI			Notate and confirm serial number of TSI camera - Contact mentor (Morris) for additional information		
		20-Aug	1	TSI serial # 105 Camera serial# C047 Camera Mac address C047-00-40-8C-44-53-F6		
18a	TSI			Replace motherboard on failed TSI computer		
		27-Aug		Replaced motherboard		
19	LGR			Replace DC/DC converters - ref. ECO-615		
				awaiting Darwin testing		
20	LGR			Verify Logger serial numbers		
		19-Aug	1	Serial numbers: SMET 7115; SKY 5962 ; Gnd 5966 spare 5970 spare 5967		
21	UPS					
		20-Aug	1	Replaced batterries 240V APC UPS in E-Van		
22	BBSS			Verify Observers using GCS properly Receive and store GCS desiccant		
		21-Aug		Desiccant hand carried and stored; Hymson operates GCS correctly		
		25-Aug		Myra operates GCS correctly		
		26-Aug		Taddy operates GCS correctly		
23	BBSS	_0 / (49		Perform electrolyser routine maintenance		
		20-Aug	4	In Progress		
		21-Aug	4	Completed		

	SITE TASKS					
	High priority / usually non-routine		Low p	oriority / usually routine Completed		
Priority	System	Date Completed (dd/Month)	Service Time (hours)	Tasks For each priority item insert new line (row) for each date/time entry		
24	BBSS			Take stock of spares and consumables and ammend resupply report accordingly		
		25-Aug	1	Completed resupply check list of BBSS spares with Hymson		
25	BBSS			Check and note model and type of RBL light and flourescent tubes it uses		
		21-Aug	0.5	Manus RBL Light Type NLE236 Lamp 2 x 36W G13? 26mm Bi-pin Manufac: Nordland Australia		
26	HOGEN			Check repaired water supply line		
		18-Aug		Checked repair is good		
		24-Aug		Repaired another break in water system.		
26a	HOGEN			Replace UV lamp		
		18-Aug	1	Lamp replaced		
27	HOGEN	10.4		Replace power supply and perform gas sensor calibration		
		18-Aug	1	gas sensor calibration in progress		
	LICOEN	19-Aug	1	Gas sensor calibration completed		
28	HOGEN	40.4	0	Repair HOGEN and investigate power supply issues		
00	HOOEN	18-Aug	3	Power supplies replaced		
29	HOGEN			Replace HOGEN van combustible gas sensor and adjust sensor		
				voltage as per manufacturer's instructions not to blow up sensor		
		10 Aug	2	on initial startup		
30	WND	19-Aug		completed Check all anemometer s/n's		
30	VVIND	22-Aug	1	Upper anemometer serial# 18422 lower anemometer serial#		
		ZZ-Aug	'	49705 spare snemometer serial # 31104		
31	OTHER			Review Monthly Resupply Checklist w/ Observers		
01	OTTIER	25-Aug	1	Reviewed monthly resupply list with Hymson		
32	IRT (SKY)	20 7 (49	•	Replace SKYRAD IRT		
	(3.11)	18-Aug	1	IRT replaced, serial# 1845 replaced with serial#867 at 03:15utc		
33	OTHER			Install new water pump and connect to water tanks; identify		
				suitable wash basin location and measure and note lengths of pipe		
				required to connect to it; check if wash basin can be purchased in		
				Lorengau		
		22-Aug	2	Commence preparations		
1		23-Aug	6	Water pump connected and tested, awaiting local electrician to		
<u> </u>		2	_	complete installtion of power outlet		
		24-Aug	3	Plumbing completed, suggest buckets be provided on site instead		
2.1	NAVA/D			of sink. (no suitable sink available in Lorengau)		
34	MWR		4	Replace Teflon window		
0.5	OTUED		1	Preventative maintenance: teflon window replaced		
35	OTHER	10 4		Perform routine maintenance per Maintenance Checklist		
-		19-Aug		In progress Pouting maintanance complete		
36	VANS	25-Aug		Routine maintenance complete Pressure-wash outside of vans		
30	VAINO			1 1000ule-wash outside of valis		
	SHIPPING			List items to be shipped following visit		
				Ship replaced SKYRAD IRT to SGP (fwd to PNNL)		
				Ship MMCR calibration kit to SGP (fwd to PNNL)		
\vdash				Ship store vault to Darwin		
	FUTURE			List items needed for future visits (spares, etc.)		
	NEEDS			(-1		
			-	· · · · · · · · · · · · · · · · · · ·		

SITE TASKS				
	High priority / usually non-routine Low p		Low p	riority / usually routine Completed
Priority	System	Date Completed (dd/Month)	Service Time (hours)	Tasks For each priority item insert new line (row) for each date/time entry
		24-Aug		Tool replacement required
				2 spare WTP level switches. SAP mat no 101228
				Hogen biannual maintenance kit
				Hogen annual maintenance kit
				Paint to paint VSAT dish
				Paint to seal fibroglass on instrument stands (SKYRAD,GNDRAD)
		24-Aug		HOGEN calibration gas
		24-Aug		HOGEN master power supply
		25-Aug		UV Lamp